

6.3. *Reporting of Low Level Wind Shear*

6.3.1. Pilots encountering wind shear shall report to ATC as soon as possible, when reporting it on radio telephony, the information should be transmitted in the following order

- a) Aircraft Call Sign;
- b) WIND SHEAR Report;
- c) Time (occurrence);
- d) Position (of wind shear);
- e) Intensity (moderate, strong or severe); and
- f) Average Height of Wind Shear Layer.

6.3.2. On receipt of wind- shear report from a pilot, ATC will pass it to other aircraft in the vicinity. This will also be broadcasted in the ATIS for the next half an hour unless subsequent report indicates that wind shear no longer exists.